ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 8 | Kodigehalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0603 | NA | Handi gud Road |
| **Segment No.** | **Total Length (m)** | |
| 8/S-W0603/S103200 | 23.53 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 23.53 | 77.572956 | 13.049149 | 77.572786 | 13.049018 | Handi gud Cross road | Dead End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to road, Drain and Footpath in main and cross roads of CQAL Layout in Ward No 08 Kodigehalli | 5000000 | 2016-17 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2016 - 2017 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | Providing and laying CC Road. | 008-17-000031 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/28/2017-18 | 19/04/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 13/12/2017 | 12/12/2018 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Executive Engineer KRIDL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9449863065 | | |

## Field Inspection Details

**Number of Trees**

2

**Any Other Information**

**Name**

Mohammed liakath ali

**Date of Inspection**

05/01/2018

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 06/01/2018 | 04/02/2018 | As proposed. |
| SE | Vasu K M | 06/01/2018 | 04/02/2018 | COMPLETED |
| EE | Mohandas H.T | 05/01/2018 | 04/02/2018 | Verified |
| AEE | H Ranganath | 05/01/2018 | 04/02/2018 | Verified |
| AE | Mohammad Liakath Ali | 05/01/2018 | 04/02/2018 | Mobile Verification Done |
| AE | Mohammed Liakath Ali | 05/01/2018 | 04/02/2018 | Forwarded |

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 8 | Kodigehalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0611 | NA | JK Tyre Showroom |
| **Segment No.** | **Total Length (m)** | |
| 8/S-W0611/S041355 | 134.61 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 134.61 | 77.572606 | 13.047276 | 77.573046 | 13.048414 | Ring Road | Bhadrappa Layout main Road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to road, drain and Footpath in Main and cross roads of CQAL layout in ward No 08, Kodigehalli | 5000000 | 2016-17 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2016 - 2017 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | Providing RCC Drain on Left side | 008-17-000031 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/26/2017-18 | 19/04/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 13/12/2017 | 12/12/2018 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Executive Engineer KRIDL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9449863065 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | Mohamed liakath ali |
| **Date of Inspection** | **Remarks** | |
| 05/01/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 06/01/2018 | 04/02/2018 | As proposed. |
| SE | VASU K M | 06/01/2018 | 04/02/2018 | COMPLETED |
| EE | Mohandas H.T | 05/01/2018 | 04/02/2018 | Verified |
| AEE | H Ranganath | 05/01/2018 | 04/02/2018 | Verified |
| AE | Mohammad Liakath Ali | 05/01/2018 | 04/02/2018 | Mobile Verification Done |
| AE | Mohammad Liakath Ali | 05/01/2018 | 04/02/2018 | Forwarded |

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 8 | Kodigehalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0605 | NA | Bhadrappa Layout |
| **Segment No.** | **Total Length (m)** | |
| 8/S-W0605/S102940 | 20.66 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 20.66 | 77.573073 | 13.048983 | 77.572929 | 13.048860 | Cross road | Dead end |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to road, Drain and Footpath in main and cross roads of CQAL Layout in Ward No 08 Kodigehalli | 5000000 | 2016-17 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2016 - 2017 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | Providing and laying CC Road. | 008-17-000031 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/28/2017-18 | 19/04/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 13/12/2017 | 12/12/2018 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Executive Engineer KRIDL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9449863065 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | Mohammed liakath ali |
| **Date of Inspection** | **Remarks** | |
| 05/01/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 06/01/2018 | 04/02/2018 | As proposed. |
| SE | VASU K M | 06/01/2018 | 04/02/2018 | COMPLETED |
| EE | Mohandas H.T | 05/01/2018 | 04/02/2018 | Verified |
| AEE | H Ranganath | 05/01/2018 | 04/02/2018 | Verified |
| AE | Mohammad Liakath Ali | 05/01/2018 | 04/02/2018 | Mobile Verification Done |
| AE | Mohammed Liakath Ali | 05/01/2018 | 04/02/2018 | Forwarded |